

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor

Kathleen Clarke Executive Director

Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 SPECTION REPORT PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax) 801-538-7223 (TDD) Partial: X Complete: Exploration: Inspection Date & Time: April 29, 1999, 9:30 AM to 12:30 PM

Date of Last Inspection: March 30, 1999

Mine Name: Wellington Preparation Plant County: Carbon Permit Number: ACT/007/012

Permittee and/or Operator's Name: Nevada Electric Investment Company (NEICO)

Business Address: c/o Mt. Nebo Scientific, Box 337, Springville, UT

Type of Mining Activity: Underground_ Surface_ Prep. Plant X Other_

State Officials(s): Paul Baker

Company Official(s): Patrick Collins and Vicky Miller

Federal Official(s): None

Weather Conditions: Cloudy, 40's, rain showers

Existing Acreage: Permitted-1720 Disturbed-356 Regraded-1.5 Seeded-1.5 Bonded-177

Increased/Decreased: Permitted-<u>0</u> Disturbed-<u>0</u> Regraded-<u>0</u> Seeded-<u>0</u> Bonded-<u>0</u>
Status: _Exploration/_X_Active/_Inactive/_Temporary Cessation/_Bond Forfeiture

Reclamation (_Phase I/_Phase II/_Final Bond Release/_Liability_Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.

a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.

b. For partial inspections check only the elements evaluated.

2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.

3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.

4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	П	[X]	П
2.	SIGNS AND MARKERS	[X]	П	Ш	\Box
3.	TOPSOIL	[X]	П	[X]	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	Ц	Ц	Ц
	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	Ц	Ц	Ц
	OTHER SEDIMENT CONTROL MEASURES	[X]	Ц	[X] [.]	Ц
	WATER MONITORING	П	Ц	Ц	Ц
e.	EFFLUENT LIMITATIONS	Ц			
5.	EXPLOSIVES	П	Ц	Щ	ĻĻ
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	Ц	Ц	Щ	H
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	Ħ	Ц	냁
8.	NONCOAL WASTE	[X]	П	[X]	Ш
9.	PROTECTION OF FISH, WILDLIFE AND	<i>e</i> 3		r 3	r ı
4.0	RELATED ENVIRONMENTAL VALUES	Ц		Ц	Η
10.	SLIDES AND OTHER DAMAGE	H	Ħ	H	片
11.	CONTEMPORANEOUS RECLAMATION	Ц	Ӊ	Ц	ᆛ
12.	BACKFILLING AND GRADING	Ц	Ӊ		Ӊ
13.	REVEGETATION	[X]	H	H	<u> </u>
14.	SUBSIDENCE CONTROL	Ц	H	H	片
15.	CESSATION OF OPERATIONS	П	Ц	Ц	П
16.	ROADS:	CX73	r 7	r 3	r 1
	CONSTRUCTION/MAINTENANCE/SURFACING		Ц	Ц	. 1
	DRAINAGE CONTROLS	Ц	П	H	냁
17.	OTHER TRANSPORTATION FACILITIES	[X]		<u>[]</u>	H
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	Ц	Ц	Ц	Η
19.	AVS CHECK (4th Quarter-April, May, June)_(date)	Ц	П	Ц	Η
20.	AIR QUALITY PERMIT		ĹΪ		H
21.	BONDING & INSURANCE	П	П	П	ΤŢ

INSPECTION REPORT

(Continuation sheet) Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: April 29, 1999

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits, Change, Transfer, Renewal, Sale

The postmining land use change/bond release have been reviewed, and the Division is awaiting further assurances that the land will be used for an industrial postmining land use. The permit transfer application also appears to be contingent on the bond release.

On April 26, 1999, the Division extended the abatement dat for violation N98-41-5-1 to May 10, 1999. Although the abatement for this violation is currently tied to approval of the postmining land use change and bond release, Mr. Collins and I discussed ways to abate the violation without having to gain approval of the rest of this amendment. The operator expects to submit a map showing the berm and to breach it. The Division would also need cross sections and a volume for the enlarged topsoil pile.

3. Topsoil

We checked one of the areas from which topsoil was moved last fall, but we found no seedlings. We believe it had been too dry, but recent rains should allow for germination and, we hope, establishment.

4. Hydrologic Balance

c. Other Sediment Control Measures.

There are a few areas where the straw bales need to be maintained or replaced. The straw bales along the railroad tracks appear to still be functioning, but they are old and should be replaced soon. There are also a few straw bales along the road by the south side of the Siaperas Ditch that should be repaired.

8. Noncoal Waste

About a year ago, the operator, Earthco, was working to reclaim the slurry pipeline. Some sections of pipe were cut up and left near the slurry pipeline sediment pond. These need to be removed, and I see no reason for not reclaiming the remainder of the pipeline. It has not been used in several years, and with part of it reclaimed what remains could not be used.

20. Air Quality Permit

Covol has begun a daily program of watering the operational areas. This was done last year but was suspended during the winter. Watering needs to be done in accordance with the Air Quality Approval Order and may need to include the coal storage pile.

Copy of this Report:

Mailed to: James Fulton (OSM), Partick Collins (NEICO/Mt. Nebo Scientific)

Given to: Joe Helfrish (DOGM)

Inspector's Signature: Paul B. Baker #41 Date: May 14, 1999